

SITE ID	LOCATION ID	LEAD GOSSE K	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WAS PUBLI C FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE	MATERIAL	PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION	WAS PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
													PRIVATE	PRIVATE	PRIVATE	PRIVATE	PRIVATE	PRIVATE			
EPAL0002	ADAMS PL 1003	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Public	Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	Private
EPAL0003	ADAMS PL 1006	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0004	ADAMS PL 1008	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0005	ADAMS PL 1009	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0006	ADAMS PL 1014	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0007	ADAMS PL 1015	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0008	ADAMS PL 1020	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0009	ADAMS PL 1021	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0010	ADAMS PL 1026	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0011	ADAMS PL 1027	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0012	ADAMS PL 1032	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0013	ADAMS PL 1033	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0014	ADAMS PL 122	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0015	ADAMS PL 128	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0016	ADAMS PL 134	N	SF	Non-Lead - Copper	N	0.75	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		0.75	1953	FILED INSPECTION ONLY	Y	2022	VISUAL INSP AT METER	
EPAL0017	AMPHITHEATER	N	NONRES	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic		1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP AT METER	
EPAL0018	AMSTERDAM CT 300	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1976	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0019	AMSTERDAM CT 301	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1976	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0020	AMSTERDAM CT 307	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1976	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0021	AMSTERDAM CT 312	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1976	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0022	AMSTERDAM CT 313	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1976	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0023	AMSTERDAM CT 319	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1976	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0024	AMSTERDAM CT 322	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1976	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0025	AMSTERDAM CT 325	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1976	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0026	AMSTERDAM CT 331	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1976	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0027	ANGELA CT 517	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0028	ANGELA CT 518	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0029	ANGELA CT 519	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0030	ANGELA CT 520	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0031	ANGELA CT 522	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0032	ANGELA CT 523	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0033	ANGELA CT 524	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0034	ANGELA CT 525	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0035	ANGELA CT 526	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0036	ANGELA CT 527	N	SF	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0037	ANNE ST S 200	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0038	ANNE ST S 203	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0039	ANNE ST S 204	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0040	ANNE ST S 209	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0041	ANNE ST S 212	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0042	ANNE ST S 215	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0043	ANNE ST S 221	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0044	ANNE ST S 222	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0045	ANNE ST S 228	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0046	ANNE ST S 231	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0047	ANNE ST S 239	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0048	ANNE ST S 240	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0049	ANNE ST S 247	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0050	ANNE ST S 252	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0051	ANNE ST S 257	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0052	ANNE ST S 258	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0053	ANNE ST S 264	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0054	ANNE ST S 265	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0055	ANNE ST S 270	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0056	ANNE ST S 276	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0057	ANNE ST S 309	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0057	ANNE ST S 310	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0058	ANNE ST S 315	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0059	ANNE ST S 316	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0060	ANNE ST S 322	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0061	ANNE ST S 323	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0062	ANNE ST S 328	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper		1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0063	ANNE ST S 331	N	SF	Non-Lead - Plastic	N	1.00	2015														



SITE ID	LOCATION ID	LEAD GOOSNEC K	BUILDING TYPE	PUBLIC	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WASPUBLIC IC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL	PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION	PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
				PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PRIVATE	PRIVATE		PRIVATE	PRIVATE	PRIVATE					
EPAL0128	ARTHUR CT 415	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	Private
EPAL0129	ARTHUR CT 416	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0130	ARTHUR CT 419	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0131	ARTHUR CT 420	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0132	ARTHUR CT 421	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0133	ARTHUR CT 422	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0134	ARTHUR CT 425	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0135	ARTHUR CT 426	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0136	ARTHUR CT 427	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0137	ARTHUR CT 428	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0138	ARTHUR CT 431	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0139	ARTHUR CT 432	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0140	ARTHUR CT 434	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0141	ARTHUR CT 437	N	SF	Non-Lead - Copper	N	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1988	INSTALLED AFTER LEAD BAN	Y	1988	VISUAL INSP AT METER	
EPAL0142	BIRCH ST S 100	N	SCH/CC	Non-Lead - Copper	Y	2.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	2.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0143	BIRCH ST S 117	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0144	BIRCH ST S 120	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP AT METER	
EPAL0145	BIRCH ST S 121	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0146	BIRCH ST S 126	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0147	BIRCH ST S 127	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0148	BIRCH ST S 132	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0149	BIRCH ST S 133	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0150	BIRCH ST S 138	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0151	BIRCH ST S 139	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1970	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	
EPAL0152	BIRCH ST S 214	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0153	BIRCH ST S 215	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0154	BIRCH ST S 220	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0155	BIRCH ST S 221	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0156	BIRCH ST S 226	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0157	BIRCH ST S 227	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0158	BIRCH ST S 232	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0159	BIRCH ST S 233	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0160	BIRCH ST S 238	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0161	BIRCH ST S 239	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1970	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	
EPAL0162	BIRCH ST S 245	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0163	BIRCH ST S 304	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0164	BIRCH ST S 308	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0165	BIRCH ST S 314	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1970	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	
EPAL0166	BIRCH ST S 315	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0167	BIRCH ST S 320	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0168	BIRCH ST S 321	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0169	BIRCH ST S 326	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0170	BIRCH ST S 327	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0171	BIRCH ST S 329	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1970	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	
EPAL0172	BIRCH ST S 331	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1970	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	
EPAL0173	BIRCH ST S 332	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	1955	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL0174	BIRCH ST S 333	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0175	BIRCH ST S 338	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1970	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	
EPAL0176	BIRCH ST S 338	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1970	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	
EPAL0177	BIRCH ST S 414	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	0.75	1970	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	
EPAL0178	BLUEBIRD LN 216	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0179	BLUEBIRD LN 218	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0180	BLUEBIRD LN 222	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0181	BLUEBIRD LN 224	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0182	BLUEBIRD LN 228	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0183	BLUEBIRD LN 230	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0184	BLUEBIRD LN 234	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0185	BLUEBIRD LN 236	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0186	BLUEBIRD LN 240	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0187	BLUEBIRD LN 242	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1985	INSTALLATION RECORD	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL0188	CARTER CT 552	N	NONRES	Non-Lead - Copper	N	2.00	1990	INSTALLED AFTER LEAD BAN	Y	1990	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1990	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0189	CARTER CT 553	N	NONRES	Non-Lead - Copper	N	2.00	1990	INSTALLED AFTER LEAD BAN	Y	1990	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1990	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0190	CARTER CT 557	N	NONRES	Non-Lead - Copper	N	2.00	1990	INSTALLED AFTER LEAD BAN	Y	1990	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1990	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0191	CARTER CT 558	N	NONRES	Non-Lead - Copper	N	2.00	1990	INSTALLED AFTER LEAD BAN	Y	1990	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1990	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	
EPAL0192	CARTER CT 569	N	NONRES	Non-Lead - Copper	N	2.00	1990	INSTALLED AFTER LEAD BAN	Y	1990	VISUAL INSP DURING INSTALL OR REPAIR</									



SITE ID	LOCATION ID	LEAD GOOSNECK	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WAS PUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes On Basis Of Material Classification - STREET SIDE OR PUBLIC	PRIVATE MATERIAL	PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION	PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes On Basis Of Material Classification - PROPERTY SIDE OR PRIVATE																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
																					PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC



SITE ID	LOCATION ID	LEAD GOOSE K	BUILDING TYPE	PUBLIC MATERAIL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIRAL CLASSIFICATION	WASPUBLIC IC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL		PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIRAL CLASSIFICATION	PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
													PRIVATE	PRIVATE							
EPAL0383	FIRST ST E 516	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Private	
EPAL0384	FIRST ST E 522	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0385	FIRST ST E 522	N	SF	Unknown - Likely Lead	UNK	UNK	1950	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1950	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER		
EPAL0386	FIRST ST E 709	N	SF	Unknown - Likely Lead	UNK	UNK	1950	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1950	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER		
EPAL0387	FIRST ST E 710	Y	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0388	FIRST ST E 715	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0389	FIRST ST E 716	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0391	FIRST ST E 721	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0392	FIRST ST E 724	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0393	FIRST ST E 803	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0394	FIRST ST E 804	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0395	FIRST ST E 809	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0396	FIRST ST E 810	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0397	FIRST ST E 816	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0398	FIRST ST E 817	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0399	FIRST ST E 820	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0400	FIRST ST E 821	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2008	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0401	FIRST ST E 826	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0402	FIRST ST E 909	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0403	FIRST ST W 103	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0404	FIRST ST W 104	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0405	FIRST ST W 115	N	NONRES	Unknown - Likely Lead	UNK	UNK	1950	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1950	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER		
EPAL0406	FIRST ST W 121	N	SF	Unknown - Likely Lead	UNK	UNK	1950	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1950	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER		
EPAL0407	FIRST ST W 121	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0408	FIRST ST W 122	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0409	FIRST ST W 222	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	1950	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0410	FIRST ST W 223	N	SF	Unknown - Likely Lead	UNK	UNK	1950	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1950	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER		
EPAL0411	FIRST ST W 515	N	SF	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2007	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL0412	FLORAL DR 11	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0413	FLORAL DR 13	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0414	FLORAL DR 15	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0415	FLORAL DR 17	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0416	FLORAL DR 19	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0417	FLORAL DR 21	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0418	FLORAL DR 3	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0419	FLORAL DR 5	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0420	FLORAL DR 7	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0421	FLORAL DR 9	N	SF	Non-Lead - Copper	N	1.00	1986	Installation record	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1986	INSTALLATION RECORD	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0422	FORD ST 707	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0423	FORD ST 710	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0424	FORD ST 718	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0425	FORD ST 736	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0426	FORD ST 738	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0427	FORD ST 740	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL0428	FOURTH ST W 1003	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0429	FOURTH ST W 1009	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0430	FOURTH ST W 1011	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0431	FOURTH ST W 1019	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0432	FOURTH ST W 1103	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0433	FOURTH ST W 1104	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0434	FOURTH ST W 1109	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0435	FOURTH ST W 1115	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0436	FOURTH ST W 1121	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0437	FOURTH ST W 1127	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0438	FOURTH ST W 1203	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0439	FOURTH ST W 1209	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0440	FOURTH ST W 1215	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0441	FOURTH ST W 1220	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0442	FOURTH ST W 1221	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0443	FOURTH ST W 1227	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0444	FOURTH ST W 1338	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0445	FOURTH ST W 1343	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0446	FOURTH ST W 1348	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0447	FOURTH ST W 1349	N	MF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0448	FOURTH ST W 1351	N	MF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL0449	FOURTH ST W 1357	N	MF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N			Unable to	



SITE ID	LOCATION ID	LEAD GOOSNEC K	BUILDING TYPE	PUBLIC MATERIAL		WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION		WASPUBLIC IC FIELD VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION		Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL		PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION		PRIVATE MATERIAL FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION		Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
				PUBLIC	PUBLIC				PUBLIC	PUBLIC			PRIVATE	PRIVATE		PRIVATE	PRIVATE			PRIVATE	PRIVATE					
EPAL0509	HEDEGEWOOD LN 706	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record		Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N								Unable to obtain any documents or records to indicate service material type	
EPAL0510	HEDEGEWOOD LN 712	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record		Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N								Unable to obtain any documents or records to indicate service material type	
EPAL0511	HEDEGEWOOD LN 723	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record		Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N								Unable to obtain any documents or records to indicate service material type	
EPAL0512	HEDEGEWOOD LN 718	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record		Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N								Unable to obtain any documents or records to indicate service material type	
EPAL0513	HEDEGEWOOD LN 719	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record		Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N								Unable to obtain any documents or records to indicate service material type	
EPAL0514	HEDEGEWOOD LN 723	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record		Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N								Unable to obtain any documents or records to indicate service material type	
EPAL0515	HEDEGEWOOD LN 724	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record		Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N								Unable to obtain any documents or records to indicate service material type	
EPAL0516	HELEN ST S 204	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0517	HELEN ST S 209	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0518	HELEN ST S 215	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0519	HELEN ST S 216	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0520	HELEN ST S 221	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0521	HELEN ST S 222	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0522	HELEN ST S 227	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0523	HELEN ST S 228	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0524	HELEN ST S 233	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0525	HELEN ST S 234	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0526	HELEN ST S 240	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0527	HELEN ST S 241	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0528	HELEN ST S 245	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0529	HELEN ST S 246	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0530	HELEN ST S 251	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0531	HELEN ST S 252	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0532	HELEN ST S 257	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0533	HELEN ST S 260	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0534	HELEN ST S 263	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0535	HELEN ST S 269	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0536	HELEN ST S 270	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0537	HELEN ST S 275	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0538	HELEN ST S 276	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0539	HELEN ST S 303	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0540	HELEN ST S 304	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0541	HELEN ST S 309	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0542	HELEN ST S 310	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0543	HELEN ST S 315	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0544	HELEN ST S 316	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0545	HELEN ST S 321	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0546	HELEN ST S 322	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0547	HELEN ST S 327	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0548	HELEN ST S 328	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0549	HELEN ST S 333	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0550	HELEN ST S 334	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0551	HELEN ST S 340	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0552	HELEN ST S 341	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0553	HELEN ST S 342	N	SF	Non-Lead - Plastic	N	1.00	2020	INSTALLED AFTER LEAD BAN		Y	2020	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	0.75	1964	INSTALLATION RECORD	Y	2020	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0554	HIGHVIEW LN 618	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0555	HIGHVIEW LN 620	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0556	HIGHVIEW LN 622	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0557	HIGHVIEW LN 626	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0558	HIGHVIEW LN 628	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0559	HIGHVIEW LN 644	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0560	HIGHVIEW LN 645	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0561	HIGHVIEW LN 646	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0562	HIGHVIEW LN 647	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0563	HIGHVIEW LN 703	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0564	HIGHVIEW LN 704	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0565	HIGHVIEW LN 705	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0566	HIGHVIEW LN 706	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN		Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR							
EPAL0567	HIGHVIEW LN 725	N	SF	Non-Lead - Copper	N	1.00	2																			







SITE ID	LOCATION ID	LEAD GOOSNECK	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WASPUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes On Basis Of Material Classification - Street Side Or Public	PRIVATE MATERIAL		PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION		PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION		Notes On Basis Of Material Classification - Property Side Or Private
													PRIVATE	PRIVATE			PRIVATE	PRIVATE			PRIVATE	PRIVATE	
EPAL0759	JOHN ST S 236	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N		PUBLIC	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0760	JOHN ST S 239	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0761	JOHN ST S 240	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0762	JOHN ST S 244	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0763	JOHN ST S 301	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL0764	JOHN ST S 304	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0765	JOHN ST S 305	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0766	JOHN ST S 310	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0767	JOHN ST S 311	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0768	JOHN ST S 315	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0769	JOHN ST S 316	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0770	JOHN ST S 319	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0771	JOHN ST S 320	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	1940	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0772	JOHN ST S 329	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	1940	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0773	JOHN ST S 337	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0774	JOHN ST S 338	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0775	JOHN ST S 341	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0776	JOHN ST S 342	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1940	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0777	JOHN ST S 348	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0778	JOHN ST S 414	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0779	JOHN ST S 415	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0780	JOHN ST S 417	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0781	JOHN ST S 421	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0782	JOHN ST S 422	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0783	JOHN ST S 423	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0784	JOHN ST S 427	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	1940	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0785	JOHN ST S 428	N	SF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0786	JOHN ST S 434	N	SF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0787	JOHN ST S 524	N	SF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0788	JOHN ST S 545	N	SCH/CC	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0789	JOHN ST S 600	N	SF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0790	JOHN ST S 602	N	SF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0791	JOHN ST S 604	N	SF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0792	JOHN ST S 606	N	SF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0793	JOHN ST S 700	N	MF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0794	JOHN ST S 706	N	MF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0795	JOHN ST S 712	N	MF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0796	JOHN ST S 718	N	MF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0797	JOHN ST S 724	N	MF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0798	JOHN ST S 730	N	MF	Unknown - Likely Lead	UNK	UNK	1977	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1977	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER				
EPAL0799	JOSEPH ST S 121	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0800	JOSEPH ST S 124	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0801	JOSEPH ST S 208	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0802	JOSEPH ST S 209	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0803	JOSEPH ST S 215	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0804	JOSEPH ST S 216	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0805	JOSEPH ST S 221	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0806	JOSEPH ST S 222	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0807	JOSEPH ST S 225	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0808	JOSEPH ST S 228	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0809	JOSEPH ST S 233	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0810	JOSEPH ST S 236	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0811	JOSEPH ST S 239	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0812	JOSEPH ST S 245	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0813	JOSEPH ST S 303	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0814	JOSEPH ST S 304	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0815	JOSEPH ST S 309	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0816	JOSEPH ST S 310	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0817	JOSEPH ST S 315	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0818	JOSEPH ST S 316	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0819	JOSEPH ST S 321	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0820	JOSEPH ST S 322	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0821	JOSEPH ST S 327	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0822	JOSEPH ST S 328	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0823	JOSEPH ST S 333	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0824	JOSEPH ST S 334	N	SF	Unknown - Likely Lead	UNK	UNK	1958	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1958	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL0825																							



SITE ID	LOCATION ID	LEAD GOOSNEC K	BUILDING TYPE	PUBLIC MATERIAL		WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION		WAS PUBLIC IC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION		PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION		Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL	PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION		PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION		PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION		Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
				PUBLIC	PUBLIC				PUBLIC	PUBLIC		PUBLIC	PUBLIC	PUBLIC	PUBLIC					PRIVATE	PRIVATE		PRIVATE	PRIVATE	PRIVATE		
EPAL0884	KENNEDY AVE E 303	N	NONRES	Non-Lead - Copper	N	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Private								
EPAL0885	KENNEDY AVE E 307	N	NONRES	Non-Lead - Copper	N	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0886	KENNEDY AVE E 309	N	NONRES	Non-Lead - Copper	N	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0887	KENNEDY AVE W 225	N	NONRES	Non-Lead - Copper	N	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0888	KENNEDY AVE W 425	N	NONRES	Non-Lead - Copper	N	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0889	KENNEDY AVE W 800	N	NONRES	Non-Lead - Copper	N	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0890	KIMBERLY AVE E 1002	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0891	KIMBERLY AVE E 1003	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0892	KIMBERLY AVE E 1004	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0893	KIMBERLY AVE E 1008	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0894	KIMBERLY AVE E 1013	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0895	KIMBERLY AVE E 1014	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0896	KIMBERLY AVE E 1020	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0897	KIMBERLY AVE E 1024	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0898	KIMBERLY AVE E 1025	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0899	KIMBERLY AVE E 1026	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0900	KIMBERLY AVE E 103	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER									
EPAL0901	KIMBERLY AVE E 1030	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0902	KIMBERLY AVE E 1032	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0903	KIMBERLY AVE E 1035	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0904	KIMBERLY AVE E 1049	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0905	KIMBERLY AVE E 104	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER									
EPAL0906	KIMBERLY AVE E 1045	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0907	KIMBERLY AVE E 1053	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0908	KIMBERLY AVE E 1061	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N		Unable to obtain any documents or records to	Unknown - Likely Lead	UNK	1960	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0909	KIMBERLY AVE E 110	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0910	KIMBERLY AVE E 114	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0911	KIMBERLY AVE E 120	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0912	KIMBERLY AVE E 125	N	SCH/CC	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER									
EPAL0913	KIMBERLY AVE E 204	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0914	KIMBERLY AVE E 217	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Unable to obtain any documents or records to indicate service material type								
EPAL0915	KIMBERLY AVE E 309	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0916	KIMBERLY AVE E 313	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0917	KIMBERLY AVE E 317	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0918	KIMBERLY AVE E 318	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0919	KIMBERLY AVE E 403	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0920	KIMBERLY AVE E 404	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0921	KIMBERLY AVE E 410	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0922	KIMBERLY AVE E 415	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0923	KIMBERLY AVE E 416	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0924	KIMBERLY AVE E 421	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER									
EPAL0925	KIMBERLY AVE E 422	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0926	KIMBERLY AVE E 424	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0927	KIMBERLY AVE E 503	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0928	KIMBERLY AVE E 504	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0929	KIMBERLY AVE E 509	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0930	KIMBERLY AVE E 515	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0931	KIMBERLY AVE E 521	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0932	KIMBERLY AVE E 600	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0933	KIMBERLY AVE E 602	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0934	KIMBERLY AVE E 603	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0935	KIMBERLY AVE E 609	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0936	KIMBERLY AVE E 613	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0937	KIMBERLY AVE E 614	N	SCH/CC	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0938	KIMBERLY AVE E 620	N	SCH/CC	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL0939	KIMBERLY AVE E 621	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0940	KIMBERLY AVE E 703	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0941	KIMBERLY AVE E 711	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0942	KIMBERLY AVE E 712	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0943	KIMBERLY AVE E 715	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0944	KIMBERLY AVE E 716	N	NONRES	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0945	KIMBERLY AVE E 719	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0946	KIMBERLY AVE E 722	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0947	KIMBERLY AVE E 723	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0948	KIMBERLY AVE E 728	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL0949	KIMBERLY AVE E 729	N	SF	Non-Lead - Plastic	UNK	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2													



SITE ID	LOCATION ID	LEAD GOSNEC K	BUILDING TYPE	PUBLIC MATERAIL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WASPUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL		PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION		PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION		Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
													PRIVATE	PRIVATE			PRIVATE	PRIVATE			PRIVATE	PRIVATE	
EPAL1009	KIMBERLY AVE W 314	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR	Public	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N			Private	Unable to obtain any documents or records to indicate service material type	
EPAL1010	KIMBERLY AVE W 410	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1011	KIMBERLY AVE W 409	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1012	KIMBERLY AVE W 413	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1013	KIMBERLY AVE W 416	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1014	KIMBERLY AVE W 419	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1015	KIMBERLY AVE W 426	N	NONRES	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1016	KIMBERLY AVE W 510	N	NONRES	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1017	KIMBERLY AVE W 545	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1018	KIMBERLY AVE W 600	N	NONRES	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1019	KIMBERLY AVE W 615	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1020	KIMBERLY AVE W 627	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1021	KIMBERLY AVE W 633	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1022	KIMBERLY AVE W 639	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1023	KIMBERLY AVE W 647	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1024	KIMBERLY AVE W 650	N	NONRES	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1025	KIMBERLY AVE W 652	N	NONRES	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1026	KIMBERLY AVE W 703	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1027	KIMBERLY AVE W 710	N	NONRES	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1028	KIMBERLY AVE W 717	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1029	KIMBERLY AVE W 720	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1030	KIMBERLY AVE W 730	N	NONRES	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1031	KIMBERLY AVE W 733	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1032	KIMBERLY AVE W 760	N	NONRES	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1033	KIMBERLY AVE W 809	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1034	KIMBERLY AVE W 817	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1035	KIMBERLY AVE W 825	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1036	KIMBERLY AVE W 837	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1037	KIMBERLY AVE W 909	N	SF	Non-Lead - Plastic	N	1.00	2013	INSTALLED AFTER LEAD BAN	Y	2013	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type	
EPAL1038	KITTY CT 1	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1039	KITTY CT 12	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1040	KITTY CT 13	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1041	KITTY CT 15	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1042	KITTY CT 18	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1043	KITTY CT 19	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1044	KITTY CT 2	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1045	KITTY CT 22	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1046	KITTY CT 400	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1047	KITTY CT 442	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1048	KITTY CT 444	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1049	KITTY CT 6	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1050	KITTY CT 7	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1051	KITTY CT 9	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1052	KNOEDLER ST 303	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1053	KNOEDLER ST 308	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1054	KNOEDLER ST 309	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1055	KNOEDLER ST 314	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1056	KNOEDLER ST 315	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1057	KNOEDLER ST 321	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1058	KNOEDLER ST 327	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1059	KOKKE LN 427	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1060	KOKKE LN 504	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1061	KOKKE LN 505	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1062	KOKKE LN 510	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1063	KOKKE LN 511	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1064	KOKKE LN 516	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1065	KOKKE LN 517	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1066	KOKKE LN 604	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1067	KOKKE LN 605	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL1068	KOKKE LN 610	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN															



[illegible]



SITE ID	LOCATION ID	LEAD GOOSNECK	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WASPUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL	PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION	PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
EPAL1257	MAES AVE E 605	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Lead	0.75	1957	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	Unable to obtain any documents or records to indicate service material type
EPAL1258	MAES AVE E 610	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1259	MAES AVE E 611	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1260	MAES AVE E 617	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Lead	0.75	1957	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	Unable to obtain any documents or records to indicate service material type
EPAL1261	MAES AVE E 618	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1262	MAES AVE E 624	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Non-Lead - Copper	0.75	1957	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	Unable to obtain any documents or records to indicate service material type
EPAL1263	MAES AVE E 700	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1264	MAES AVE E 711	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Non-Lead - Copper	0.75	1957	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	Unable to obtain any documents or records to indicate service material type
EPAL1265	MAES AVE E 729	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Non-Lead - Plastic	1.00	1988	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	Unable to obtain any documents or records to indicate service material type
EPAL1266	MAES AVE E 800	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1267	MAES AVE E 817	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1268	MAES AVE E 850	N	NONRES	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1269	MAES AVE E 860	N	NONRES	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1270	MAES AVE E 870	N	NONRES	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1271	MAES AVE E 874	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1272	MAES AVE E 878	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1273	MAES AVE E 882	N	NONRES	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1274	MAES AVE E 888	N	NONRES	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1275	MAES AVE E 913	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1276	MAES AVE E 917	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1277	MAES AVE E 923	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1278	MAES AVE E 929	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1279	MAES AVE W 104	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1280	MAES AVE W 106	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1281	MAES AVE W 116	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1282	MAES AVE W 122	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1283	MAES AVE W 316	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1284	MAES AVE W 322	N	SF	Non-Lead - Copper	UNK	1.00	1988	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1285	MAIN ST N 114	N	NONRES	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	Unable to obtain any documents or records to indicate service material type
EPAL1286	MAIN ST N 117	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1287	MAIN ST N 120	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1288	MAIN ST N 123	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1289	MAIN ST N 129	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1290	MAIN ST N 130	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1291	MAIN ST N 132	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1292	MAIN ST N 135	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1293	MAIN ST N 136	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	1975	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	Unable to obtain any documents or records to indicate service material type
EPAL1294	MAIN ST N 141	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1295	MAIN ST N 142	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Lead	1.00	1945	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	Unable to obtain any documents or records to indicate service material type
EPAL1296	MAIN ST N 147	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1297	MAIN ST N 150	N	NONRES	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Lead	1.00	1945	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER	Unable to obtain any documents or records to indicate service material type
EPAL1298	MAIN ST N 202	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1299	MAIN ST N 208	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1300	MAIN ST N 210	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1301	MAIN ST N 216	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1302	MAIN ST N 222	N	NONRES	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1303	MAIN ST N 226	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1304	MAIN ST N 232	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1305	MAIN ST N 304	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1306	MAIN ST N 308	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1307	MAIN ST N 314	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1308	MAIN ST N 318	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1309	MAIN ST N 324	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1310	MAIN ST N 330	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Lead	1.00	1955	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1311	MAIN ST N 345	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1312	MAIN ST N 408	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1313	MAIN ST N 412	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1314	MAIN ST N 420	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1315	MAIN ST N 426	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1316	MAIN ST N 436	N	SF	Non-Lead - Copper	Y	1.00	2006	INSTALLED AFTER LEAD BAN	Y	2006	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1317	MAIN ST S 114	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1318	MAIN ST S 120	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1319	MAIN ST S 122	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1320	MAIN ST S 126	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1321	MAIN ST S 134	N	SF	Unknown - Likely Lead	UNK	UNK	1945	Other - describe in notes	N		Other - describe in notes	Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1945	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL1322	MAIN ST S 140	N	SF	Unknown - Likely Lead	UNK	UNK	194													



SITE ID	LOCATION ID	LEAD GOOSNECK	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WASPUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes On Basis Of Material Classification - STREET SIDE OR PUBLIC	PRIVATE MATERIAL		PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION	PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes On Basis Of Material Classification - PROPERTY SIDE OR PRIVATE
													PRIVATE	PRIVATE							
EPAL1382	MAPLE ST S 327	N	SF	Non-Lead - Plastic	UNK	1.00	2014	INSTALLED AFTER LEAD BAN	Y	2014	VISUAL INSP DURING INSTALL OR REPAIR	Public	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Private	
EPAL1383	MAPLE ST S 332	N	SF	Non-Lead - Plastic	UNK	1.00	2014	INSTALLED AFTER LEAD BAN	Y	2014	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1384	MAPLE ST S 333	N	SF	Non-Lead - Plastic	UNK	1.00	2014	INSTALLED AFTER LEAD BAN	Y	2014	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1385	MAPLE ST S 338	N	SF	Non-Lead - Plastic	UNK	1.00	2014	INSTALLED AFTER LEAD BAN	Y	2014	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1386	MAPLE ST S 339	N	SF	Non-Lead - Plastic	UNK	1.00	2014	INSTALLED AFTER LEAD BAN	Y	2014	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1387	MAPLE ST S 414	N	SF	Non-Lead - Plastic	UNK	1.00	2014	INSTALLED AFTER LEAD BAN	Y	2014	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1388	MAPLE ST S 415	N	SF	Non-Lead - Plastic	UNK	1.00	2014	INSTALLED AFTER LEAD BAN	Y	2014	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1389	MAPLE ST S 420	N	SF	Non-Lead - Plastic	UNK	1.00	2014	INSTALLED AFTER LEAD BAN	Y	2014	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1390	MARCELLA ST 265	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1391	MARCELLA ST 337	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1392	MARCELLA ST 345	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1393	MARCELLA ST 351-355	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1394	MARCELLA ST 401	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1395	MARCELLA ST 407	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1396	MARCELLA ST 409	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1397	MARCELLA ST 413	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1398	MARCELLA ST 417	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1399	MARCELLA ST 421	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1400	MARCELLA ST 503	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1401	MARCELLA ST 551	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1402	MARCELLA ST 557	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1403	MARCELLA ST 571	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1404	MARCELLA ST 575	N	NONRES	Unknown - Likely Lead	UNK	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1974	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1405	MATTHEW ST S 221	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1406	MATTHEW ST S 222	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1407	MATTHEW ST S 227	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1408	MATTHEW ST S 228	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1409	MATTHEW ST S 233	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1410	MATTHEW ST S 234	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1411	MATTHEW ST S 239	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1412	MATTHEW ST S 240	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1413	MATTHEW ST S 245	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1414	MATTHEW ST S 303	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1415	MATTHEW ST S 304	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1416	MATTHEW ST S 309	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1417	MATTHEW ST S 310	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1418	MATTHEW ST S 315	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1419	MATTHEW ST S 316	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1420	MATTHEW ST S 321	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1421	MATTHEW ST S 322	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1422	MATTHEW ST S 327	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1423	MATTHEW ST S 328	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1424	MATTHEW ST S 334	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1425	MATTHEW ST S 335	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1426	MATTHEW ST S 340	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1427	MATTHEW ST S 343	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1428	MATTHEW ST S 346	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1429	MATTHEW ST S 350	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1430	MATTHEW ST S 351	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1431	MATTHEW ST S 403	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1432	MATTHEW ST S 404	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1433	MATTHEW ST S 409	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1434	MATTHEW ST S 410	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1435	MATTHEW ST S 415	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1436	MATTHEW ST S 421	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1437	MATTHEW ST S 422	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1438	MATTHEW ST S 427	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1439	MATTHEW ST S 428	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1440	MATTHEW ST S 429	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1441	MATTHEW ST S 434	N	SF	Unknown - Likely Lead	UNK	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1959	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type			
EPAL1442	MUNICIPAL CENTER	N	MIX	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2008	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL1443	QAK ST E 515	N	SF	Non-Lead - Plastic	N	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1444	QAK ST E 521	N	SF	Non-Lead - Plastic	N	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1445	QAK ST E 605	N	SF	Non-Lead - Plastic	N	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1446	QAK ST E 611	N	SF	Non-Lead - Plastic	N	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1447	QAK ST E 617	N	SF	Non-Lead - Plastic	N	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1448	QAK ST E 618	N	SF	Non-Lead - Plastic	N	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1449	QAK ST E 624	N	SF	Non-Lead - Plastic	N	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL1450	OSHKOSH WAY 212	N	SF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VIS		



[illegible]



SITE ID	LOCATION ID	LEAD GOOSNECK	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WASPUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes on BASIS of MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL			BASIS OF PRIVATE MATERIAL CLASSIFICATION	WAS PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes on BASIS of MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
													PRIVATE	PRIVATE SIZE	PRIVATE INSTALL					
EPAL1632	PINE ST N 377	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR	Public	Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	Private
EPAL1633	PINE ST N 379	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1634	PINE ST N 381	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1635	PINE ST N 383	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1636	PINE ST S 134	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1637	PINE ST S 115	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1638	PINE ST S 118-120	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1639	PINE ST S 121	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1640	PINE ST S 126	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1641	PINE ST S 127	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1642	PINE ST S 132	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1643	PINE ST S 133	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1644	PINE ST S 138	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1645	PINE ST S 139	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1646	PINE ST S 145	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1647	PINE ST S 202	N	SCH/CC	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1648	PINE ST S 203	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1649	PINE ST S 207	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1650	PINE ST S 208 A	N	SCH/CC	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1650 S	PINE ST S 208 B	N	SCH/CC	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1651	PINE ST S 215	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1652	PINE ST S 221	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1653	PINE ST S 226	N	SCH/CC	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1654	PINE ST S 227	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1655	PINE ST S 232	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1656	PINE ST S 233	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1657	PINE ST S 238	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1658	PINE ST S 239	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1659	PINE ST S 244	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1660	PINE ST S 245	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1661	PINE ST S 251	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1662	PINE ST S 303	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1663	PINE ST S 307	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1664	PINE ST S 314	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1665	PINE ST S 315	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1666	PINE ST S 321	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1667	PINE ST S 326	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1668	PINE ST S 327	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1669	PINE ST S 330	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1670	PINE ST S 332	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1671	PINE ST S 333	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1672	PINE ST S 338	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1673	PINE ST S 339	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1674	PINE ST S 344	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1675	PINE ST S 345	N	SF	Non-Lead - Plastic	UNK	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2003	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2003	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1676	RAILROAD ST S 103	N	SF	Non-Lead - Copper	UNK	UNK	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	
EPAL1677	RAILROAD ST S 105	N	SF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1678	RAILROAD ST S 107	N	SF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1679	RAILROAD ST S 109	N	SF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1680	RAILROAD ST S 113	N	SF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1681	RAILROAD ST S 123	N	SF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1682	RAILROAD ST S 125	N	MF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1683	RAILROAD ST S 127	N	MF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1684	RAILROAD ST S 129	N	MF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1685	RAILROAD ST S 131	N	MF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1686	RAILROAD ST S 133	N	MF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1687	RAILROAD ST S 135	N	MF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1688	RAILROAD ST S 137	N	MF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1689	RAILROAD ST S 139	N	MF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1690	RAILROAD ST S 151	N	MF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Non-Lead - Copper	1.00	1983	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER
EPAL1691	RAILROAD ST S 153	N	SF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1692	RAILROAD ST S 157	N	SF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1693	RAILROAD ST S 159	N	SF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type
EPAL1694	RAILROAD ST S 163	N	SF	Non-Lead - Copper	UNK	UNK	1.00	1983	Installation record	Y	2025	Other - describe in notes	Documented Specs for 1" Copper Services	Unknown - Likely Lead	UNK	1983	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type



SITE ID	LOCATION ID	LEAD GOOSNEC K	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WAS PUBLIC IC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL			Basis OF PRIVATE MATERIAL CLASSIFICATION	PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
													PRIVATE	PRIVATE SIZE	PRIVATE INSTALL					
EPAL1756	RED CEDAR PARKWAY 307	N	SF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Public	PRIVATE	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Private
EPAL1757	RED CEDAR PARKWAY 309	N	SF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1758	RED CEDAR PARKWAY 313	N	SF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1759	RED CEDAR PARKWAY 315	N	SF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1760	RIVERS EDGE DR 206	N	MF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1761	RIVERS EDGE DR 209	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1762	RIVERS EDGE DR 210	N	MF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1763	RIVERS EDGE DR 215	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1764	RIVERS EDGE DR 220	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1765	RIVERS EDGE DR 225	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1766	RIVERS EDGE DR 230	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1767	RIVERS EDGE DR 235	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1768	RIVERS EDGE DR 240	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1769	RIVERS EDGE DR 250	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1770	RIVERS EDGE DR 260	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1771	RIVERS EDGE DR 265	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1772	RIVERS EDGE DR 270	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1773	RIVERS EDGE DR 275	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1774	RIVERS EDGE DR 280	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1775	RIVERS EDGE DR 290	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1776	RIVERS EDGE DR 295	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1777	RIVERS EDGE DR 300	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1778	RIVERS EDGE DR 315	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1779	RIVERS EDGE DR 320	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1780	RIVERS EDGE DR 325	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1781	RIVERS EDGE DR 330	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1782	RIVERS EDGE DR 335	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1783	RIVERS EDGE DR 410	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1784	RIVERS EDGE DR 415	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1785	RIVERS EDGE DR 420	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1786	RIVERS EDGE DR 425	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1787	RIVERS EDGE DR 430	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1788	RIVERS EDGE DR 435	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1789	RIVERS EDGE DR 440	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1790	RIVERS EDGE DR 445	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1791	RIVERS EDGE DR 450	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1792	RIVERS EDGE DR 460	N	SF	Non-Lead - Plastic	N	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1793	ROGER ST N 110	N	SF	Non-Lead - Plastic	N	1.00	2016	INSTALLED AFTER LEAD BAN	Y	2016	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2016	INSTALLED AFTER LEAD BAN	Y	2016	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1794	ROGER ST N 116	N	SF	Non-Lead - Plastic	N	1.00	2016	INSTALLED AFTER LEAD BAN	Y	2016	VISUAL INSP DURING INSTALL OR REPAIR		PRIVATE	1.00	2016	INSTALLATION RECORD	Y	2016	VISUAL INSP DURING INSTALL OR REPAIR	
EPAL1795	ROGER ST N 203	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1796	ROGER ST N 209	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1797	ROGER ST N 210	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1798	ROGER ST N 215	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1799	ROGER ST N 216	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1800	ROGER ST N 221	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1801	ROGER ST N 222	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1802	ROGER ST N 303	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1803	ROGER ST N 309	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1804	ROGER ST N 310	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1805	ROGER ST N 314	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1806	ROGER ST N 315	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1807	ROGER ST N 321	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1808	ROGER ST N 370	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1809	ROGER ST N 327	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1810	ROGER ST N 328	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1811	ROGER ST N 333	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1812	ROGER ST N 334	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1813	ROGER ST N 339	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1814	ROGER ST N 340	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1815	ROGER ST N 345	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1816	ROGER ST N 346	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1817	ROGER ST N 351	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1818	ROGER ST N 352	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1819	ROGER ST N 357	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1820	ROGER ST N 358	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1821	ROGER ST N 363	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1822	ROGER ST N 364	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL1823	ROGER ST N 369	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes					



SITE ID	LOCATION ID	LEAD GOOSNEC K	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD		PUBLIC SIZE	PUBLIC INSTALL		BASIS OF PUBLIC MATERIAL CLASSIFICATION	WAS PUBLIC IC FILED VERIFIED		DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL		PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION		PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION		PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION		Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
					PUBLIC	PRIVATE		PUBLIC	PRIVATE		PRIVATE	PRIVATE				PRIVATE	PRIVATE			PRIVATE	PRIVATE		PRIVATE	PRIVATE			
EPAL1882	SCHSELFHOUT LN 796	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR	Private								
EPAL1883	SCHSELFHOUT LN 798	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1884	SCHSELFHOUT LN 800	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1885	SCHSELFHOUT LN 802	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1886	SCHSELFHOUT LN 804	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1887	SCHSELFHOUT LN 806	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1888	SCHSELFHOUT LN 808	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1889	SCHSELFHOUT LN 810	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1890	SCHSELFHOUT LN 812	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1891	SCHSELFHOUT LN 814	N	SF	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1892	SCHSELFHOUT LN 816	N	NONRES	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1893	SCHSELFHOUT LN 819	N	NONRES	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1894	SCHSELFHOUT LN 820	N	NONRES	Non-Lead - Copper	N	1.00	2000	INSTALLED AFTER LEAD BAN	Y	2000	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2000	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1895	SCHINDLER DR 303	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1896	SCHINDLER DR 304	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1897	SCHINDLER DR 309	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1898	SCHINDLER DR 310	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1899	SCHINDLER DR 315	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1900	SCHINDLER DR 316	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1901	SCHINDLER DR 321	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1902	SCHINDLER DR 322	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1903	SCHINDLER DR 327	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1904	SCHINDLER DR 328	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1905	SCHINDLER DR 333	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1906	SCHINDLER DR 334	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1907	SCHINDLER DR 339	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1908	SCHINDLER DR 340	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1909	SCHINDLER DR 345	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1910	SCHINDLER DR 346	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1911	SCHINDLER DR 351	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1912	SCHINDLER DR 352	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1913	SCHINDLER DR 356	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1914	SCHINDLER DR 357	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1915	SCHINDLER DR 364	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1916	SCHINDLER DR 365	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1917	SCHINDLER DR 370	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1918	SCHINDLER DR 373	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1919	SCHINDLER DR 376	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1920	SCHINDLER DR 381	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1921	SCHINDLER DR 382	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1922	SCHINDLER DR 388	N	SF	Unknown - Likely Lead	UNK	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1979	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1923	SECOND ST E 103	N	SF	Unknown - Likely Lead	UNK	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1924	SECOND ST E 104	N	SF	Unknown - Likely Lead	UNK	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1925	SECOND ST E 109	N	SF	Unknown - Likely Lead	UNK	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1926	SECOND ST E 110	N	SF	Unknown - Likely Lead	UNK	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1956	Other - describe in notes	N		Unable to obtain any documents or records to indicate service material type									
EPAL1927	SECOND ST E 115	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1928	SECOND ST E 116	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1929	SECOND ST E 121	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1930	SECOND ST E 122	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1931	SECOND ST E 203	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1932	SECOND ST E 204	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1933	SECOND ST E 208	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1934	SECOND ST E 209	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1935	SECOND ST E 216	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1936	SECOND ST E 310	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1937	SECOND ST E 316	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1938	SECOND ST E 322	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1939	SECOND ST E 403	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR									
EPAL1940	SECOND ST E 409	N	SF	Non-Lead - Copper	Y	1.00	2009	INSTALLED AFTER LEAD BAN	Y	2009	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022													



[illegible]



SITE ID	LOCATION ID	LEAD GOSWEC K	BUILDING TYPE	PUBLIC MATERAIL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIRAL CLASSIFICATION	WASPUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL		PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIRAL CLASSIFICATION		PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION		Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
													PRIVATE	PRIVATE			PRIVATE	PRIVATE			PRIVATE	PRIVATE	
EPAL2131	STONE GATE DR 606	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Public	Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N				Private	Unable to obtain any documents or records to indicate service material type	
EPAL2132	STONE GATE DR 701	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2133	STONE GATE DR 707	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2134	STONE GATE DR 712	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2135	STONE GATE DR 713	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2136	STONE GATE DR 718	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2137	STONE GATE DR 719	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2138	STONE GATE DR 724	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2139	STONE GATE DR 725	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2140	STONE GATE DR 730	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2141	STONE GATE DR 731	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2142	STONE GATE DR 737	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2143	STRAWBERRY LN 619	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2144	STRAWBERRY LN 625	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2145	STRAWBERRY LN 630	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2146	STRAWBERRY LN 631	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2147	STRAWBERRY LN 637	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2148	STRAWBERRY LN 701	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2149	STRAWBERRY LN 706	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2150	STRAWBERRY LN 707	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2151	STRAWBERRY LN 712	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2152	STRAWBERRY LN 713	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2153	STRAWBERRY LN 718	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2154	STRAWBERRY LN 719	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2155	STRAWBERRY LN 724	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2156	STRAWBERRY LN 725	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2157	STRAWBERRY LN 730	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2158	STRAWBERRY LN 731	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR		Unknown - Likely Lead	UNKN	1985	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2159	SUNSET DR 1003	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2160	SUNSET DR 1004	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2161	SUNSET DR 1013	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2162	SUNSET DR 1014	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2163	SUNSET DR 1023	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2164	SUNSET DR 1024	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2165	SUNSET DR 1103	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2166	SUNSET DR 1104	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2167	SUNSET DR 1113	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2168	SUNSET DR 1114	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2169	SUNSET DR 1203	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2170	SUNSET DR 1204	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2171	SUNSET DR 1213	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2172	SUNSET DR 1214	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2173	SUNSET DR 1304	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2174	SUNSET DR 1314	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2175	SUNSET DR 1326	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2176	SUNSET DR 1402	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2177	SUNSET DR 1403	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2178	SUNSET DR 1420	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2179	SUNSET DR 1421	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2180	SUNSET DR 1432	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2181	SUNSET DR 1502	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2182	SUNSET DR 1516	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2183	SUNSET DR 1601	N	SF	Non-Lead - Plastic	N	1.00	2023	INSTALLED AFTER LEAD BAN	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR	Y	2023	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2184	SWIM LAKE	N	MIX	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2008	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER	Y	2022	VISUAL INSP AT METER		
EPAL2185	TAYLOR ST 407	N	MF	Non-Lead - Copper	N	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2186	TAYLOR ST 407	N	MF	Non-Lead - Copper	N	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2187	TAYLOR ST 412	N	SF	Non-Lead - Copper	N	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2188	TAYLOR ST 413	N	MF	Non-Lead - Copper	N	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2189	TAYLOR ST 414	N	SF	Non-Lead - Copper	N	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2190	TAYLOR ST 419	N	MF	Non-Lead - Copper	N	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.50	1992	INSTALLED AFTER LEAD BAN	Y	1992						



SITE ID	LOCATION ID	LEAD GOOSENECK	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WAS PUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERIAL		PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION		PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION		Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
													PRIVATE	PRIVATE			PRIVATE	PRIVATE			PRIVATE	PRIVATE	
EPAL2256	THERESA CT 609	N	SF	Non-Lead - Plastic	N	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Public	Non-Lead - Copper	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Private		Unable to obtain any documents or records to indicate service material type	
EPAL2257	THERESA CT 610	N	SF	Non-Lead - Plastic	N	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL2258	THERESA CT 612	N	SF	Non-Lead - Plastic	N	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR	Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	1.00	2001	INSTALLED AFTER LEAD BAN	Y	2001	VISUAL INSP DURING INSTALL OR REPAIR			Unable to obtain any documents or records to indicate service material type	
EPAL2260	THIRD ST E 103	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2260	THIRD ST E 109	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2261	THIRD ST E 115	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2262	THIRD ST E 116	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2263	THIRD ST E 121	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2264	THIRD ST E 122	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2265	THIRD ST E 203	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2266	THIRD ST E 204	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2267	THIRD ST E 209	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2268	THIRD ST E 210	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2269	THIRD ST E 215	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1940	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2270	THIRD ST E 216	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2271	THIRD ST E 221	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2272	THIRD ST E 222	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2273	THIRD ST E 303	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2274	THIRD ST E 304	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2275	THIRD ST E 309	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1940	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2276	THIRD ST E 310	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2277	THIRD ST E 315	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2278	THIRD ST E 316	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2279	THIRD ST E 321	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2280	THIRD ST E 322	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2281	THIRD ST E 403	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2282	THIRD ST E 404	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2283	THIRD ST E 409	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2284	THIRD ST E 410	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2285	THIRD ST E 415	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2286	THIRD ST E 416	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2287	THIRD ST E 422	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2288	THIRD ST E 423	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2289	THIRD ST E 503	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2290	THIRD ST E 504	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2291	THIRD ST E 505	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2292	THIRD ST E 508	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2293	THIRD ST E 510	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	1940	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2294	THIRD ST E 516	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1940	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2295	THIRD ST E 521	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2296	THIRD ST E 603	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2297	THIRD ST E 604	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2298	THIRD ST E 607	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2299	THIRD ST E 615	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2300	THIRD ST E 616	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2301	THIRD ST E 704	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2302	THIRD ST E 711	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1940	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2303	THIRD ST E 712	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1940	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2304	THIRD ST E 715	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2305	THIRD ST E 716	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1940	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2306	THIRD ST E 719	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2307	THIRD ST E 720	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2308	THIRD ST E 724	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2309	THIRD ST E 725	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1940	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2310	THIRD ST E 731	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2311	THIRD ST E 803	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Lead	0.75	1940	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2312	THIRD ST E 809	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2313	THIRD ST E 815	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2314	THIRD ST E 821	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2315	THIRD ST E 827	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	2001	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER				
EPAL2316	THIRD ST E 833	N	SF	Unknown - Likely Lead	UNK	UNK	1940	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1940	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2317	THIRD ST W 1019	N	SF	Unknown - Likely Lead	UNK	UNK	1978	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1978	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2318	THIRD ST W 1020	N	SF	Unknown - Likely Lead	UNK	UNK	1978	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1978	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2319	THIRD ST W 103	N	SF	Unknown - Likely Lead	UNK	UNK	1930	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1930	Other - describe in notes	N					Unable to obtain any documents or records to indicate service material type	
EPAL2320	THIRD ST W 107	N	SF	Unknown - Likely Lead	UNK	UNK	1930	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	1930	PREVIOUS EVAL	Y	2022	VISUAL INSP AT METER				
EPAL2321	THIRD ST W 1103	N	SF	Unknown - Likely Lead	UNK	UNK	1978	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type											



SITE ID	LOCATION ID	LEAD GOOSENICK	BUILDING TYPE	PUBLIC MATERAIL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIRAL CLASSIFICATION	WASPUBLIC IC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes On Basis Of Material Classification - STREET SIDE OR PUBLIC	PRIVATE MATERIAL		PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIRAL CLASSIFICATION	PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes On Basis Of Material Classification - PROPERTY SIDE OR PRIVATE
													PRIVATE	PRIVATE							
EPAL2381	THIRD ST W 836	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	Public	Non-Lead - Copper	1.00	2000	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR	Private	
EPAL2382	THIRD ST W 837	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2383	THIRD ST W 803	N	SF	Non-Lead - Plastic	N	1.00	2015	INSTALLED AFTER LEAD BAN	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2000	INSTALLATION RECORD	Y	2015	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2384	TREATY LN 200	N	SF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2385	TREATY LN 202	N	SF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2386	TREATY LN 206	N	SF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2387	TREATY LN 208	N	SF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2388	TRUMAN ST 1001	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2389	TRUMAN ST 1002	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2390	TRUMAN ST 1019	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2391	TRUMAN ST 1020	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2392	TRUMAN ST 1037	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2393	TRUMAN ST 1055	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2394	TRUMAN ST 749	N	SCH/CC	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2395	TRUMAN ST 753	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2396	TRUMAN ST 759	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2397	TRUMAN ST 761	N	NONRES	Non-Lead - Copper	N	2.00	1986	Diameter > 2 inches	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	2.00	1986	DIAMETER > 2"	Y	1986	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2398	UPPER HARDBALL	N	MIX	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2008	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2399	UPPER SOFTBALL	N	MIX	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2008	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2400	VAN ELZEN LN 533	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2401	VAN ELZEN LN 534	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2402	VAN ELZEN LN 539	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2403	VAN ELZEN LN 540	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2404	VAN ELZEN LN 545	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2405	VAN ELZEN LN 546	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2406	VAN ELZEN LN 551	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2407	VAN ELZEN LN 552	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2408	VAN ELZEN LN 557	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2409	VAN ELZEN LN 558	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2410	VAN ELZEN LN 563	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2411	VAN ELZEN LN 564	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2412	VAN ELZEN LN 569	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2413	VAN ELZEN LN 570	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2414	VAN ELZEN LN 578	N	SF	Non-Lead - Copper	N	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	1993	INSTALLED AFTER LEAD BAN	Y	1993	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2415	VERHAGEN PARKWAY	N	MIX	Non-Lead - Copper	Y	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2008	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2007	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2416	VILLA DR 514	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2417	VILLA DR 516	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2418	VILLA DR 520	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2419	VILLA DR 522	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2420	VILLA DR 526	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2421	VILLA DR 528	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2422	VILLA DR 532	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2423	VILLA DR 534	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2424	VILLA DR 538	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2425	VILLA DR 540	N	SF	Non-Lead - Copper	N	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Copper	1.00	2004	INSTALLED AFTER LEAD BAN	Y	2005	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2427	WALNUT ST S 114	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2428	WALNUT ST S 115	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2429	WALNUT ST S 120	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2430	WALNUT ST S 121	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2431	WALNUT ST S 126	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2432	WALNUT ST S 127	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2433	WALNUT ST S 132	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2434	WALNUT ST S 138	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2435	WALNUT ST S 139	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2436	WALNUT ST S 151	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2437	WALNUT ST S 203	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2438	WALNUT ST S 209	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2439	WALNUT ST S 214	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2440	WALNUT ST S 215	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2441	WALNUT ST S 220	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2442	WALNUT ST S 221	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2443	WALNUT ST S 226	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2444	WALNUT ST S 227	N	SF	Non-Lead - Plastic	Y	1.00	2010	INSTALLED AFTER LEAD BAN	Y	2010	VISUAL INSP DURING INSTALL OR REPAIR		Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2445	WALNUT ST S 232	N	SF	Non-Lead - Plastic	Y	1.00															



SITE ID	LOCATION ID	LEAD GOOSNECK	BUILDING TYPE	PUBLIC MATERIAL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WASPUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes On Basis Of Material Classification - STREET SIDE OR PUBLIC	PRIVATE MATERIAL	PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION	PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes On Basis Of Material Classification - PROPERTY SIDE OR PRIVATE
EPAL2508	WASHINGTON ST S 424	N	NONRES	Non-Lead - Plastic	N	12.00	1975	Field inspection only	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Public	Non-Lead - Plastic	12.00	1975	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Private
EPAL2509	WASHINGTON ST S 438	N	SF	Unknown - Likely Lead	UNK	UNK	1930	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1930	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL2510	WASHINGTON ST S 444	N	NONRES	Non-Lead - Copper	N	1.00	1976	Field inspection only	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1976	Other - describe in notes	N				Unable to obtain any documents or records to indicate service material type
EPAL2511	WASHINGTON ST S 532	N	NONRES	Non-Lead - Copper	N	1.00	1976	Field inspection only	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1976	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL2512	WASHINGTON ST S 532	N	NONRES	Non-Lead - Copper	N	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1994	INSTALLED AFTER LEAD BAN	Y	1994	VISUAL INSP AT METER		
EPAL2513	WASHINGTON ST S 534	N	SF	Unknown - Likely Lead	UNK	UNK	1930	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1930	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL2514	WASHINGTON ST S 536	N	SF	Unknown - Likely Lead	UNK	UNK	1930	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	1930	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL2515	WASHINGTON ST S 800	N	NONRES	Non-Lead - Plastic	N	6.00	2013	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	6.00	2013	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2516	WELHOUSE DR 200	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2517	WELHOUSE DR 201	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2518	WELHOUSE DR 206	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2519	WELHOUSE DR 207	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2520	WELHOUSE DR 212	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2521	WELHOUSE DR 213	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2522	WELHOUSE DR 218	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2523	WELHOUSE DR 219	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2524	WELHOUSE DR 224	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2525	WELHOUSE DR 225	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2526	WELHOUSE DR 230	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2527	WELHOUSE DR 231	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2528	WELHOUSE DR 236	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2529	WELHOUSE DR 242	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2530	WELHOUSE DR 248	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2531	WELHOUSE DR 302	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2532	WELHOUSE DR 308	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2533	WELHOUSE DR 309	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2534	WELHOUSE DR 314	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2535	WELHOUSE DR 315	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2536	WELHOUSE DR 320	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2537	WELHOUSE DR 321	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2538	WELHOUSE DR 326	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2539	WELHOUSE DR 327	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2540	WELHOUSE DR 332	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2541	WELHOUSE DR 333	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2542	WELHOUSE DR 338	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2543	WELHOUSE DR 339	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2544	WELHOUSE DR 342	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2545	WELHOUSE DR 345	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2546	WELHOUSE DR 348	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2547	WELHOUSE DR 351	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2548	WELHOUSE DR 354	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2549	WELHOUSE DR 357	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2550	WELHOUSE DR 360	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2551	WELHOUSE DR 361	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2552	WELHOUSE DR 368	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2553	WELHOUSE DR 369	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2554	WELHOUSE DR 375	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2555	WELHOUSE DR 376	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2556	WELHOUSE DR 382	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2557	WELHOUSE DR 383	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2558	WELHOUSE DR 389	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2559	WELHOUSE DR 390	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2560	WELHOUSE DR 397	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2561	WELHOUSE DR 398	N	SF	Non-Lead - Plastic	N	1.00	2024	INSTALLED AFTER LEAD BAN	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	1974	INSTALLATION RECORD	Y	2024	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2562	WHITE CEDAR PARKWAY 321	N	MF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2563	WHITE CEDAR PARKWAY 325	N	MF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2564	WHITE CEDAR PARKWAY 329	N	MF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2565	WHITE CEDAR PARKWAY 333	N	MF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2566	WHITE CEDAR PARKWAY 337	N	MF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2567	WHITE CEDAR PARKWAY 341	N	MF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2568	WHITE CEDAR PARKWAY 345	N	MF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2569	WHITE CEDAR PARKWAY 349	N	MF	Non-Lead - Plastic	N	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2017	INSTALLED AFTER LEAD BAN	Y	2017	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2570	WILBUR ST S 202	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL2571	WILBUR ST S 203	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type
EPAL2572	WILBUR ST S 210	N	SF	Unknown - Likely Lead	UNK	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	Unknown - Likely Lead	UNK	UNK	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type



SITE ID	LOCATION ID	LEAD GOSNEE K	BUILDING TYPE	PUBLIC MATERAIL	WAS PUBLICSIDE EVER LEAD	PUBLIC SIZE	PUBLIC INSTALL	BASIS OF PUBLIC MATERIAL CLASSIFICATION	WASPUBLIC FILED VERIFIED	DATE OF STREET SIDE FIELD VERIFICATION	PUBLIC METHOD OF STREET SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - STREET SIDE OR PUBLIC	PRIVATE MATERAIL	PRIVATE SIZE	PRIVATE INSTALL	BASIS OF PRIVATE MATERIAL CLASSIFICATION	WAS PRIVATE FILED VERIFIED	DATE OF PROPERTY SIDE FIELD VERIFICATION	PRIVATE METHOD OF PROPERTY SIDE FIELD VERIFICATION	Notes ON BASIS OF MATERIAL CLASSIFICATION - PROPERTY SIDE OR PRIVATE
				PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PUBLIC	PRIVATE	PRIVATE		PRIVATE	PRIVATE	PRIVATE					
EPAL2633	WILLOW ST S 342	N	SF	Unknown - Likely Lead	UNK	UNK	1935	Other - describe in notes	N		PUBLIC	Unable to obtain any documents or records to indicate service material type	PRIVATE	PRIVATE	1935	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER	Private
EPAL2634	WILLOW ST S 351	N	SF	Unknown - Likely Lead	UNK	UNK	1935	Other - describe in notes	N		PUBLIC	Unable to obtain any documents or records to indicate service material type	Non-Lead - Copper	0.75	1935	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER	
EPAL2635	WILLOW ST S 355	N	SF	Unknown - Likely Lead	UNK	UNK	1935	Other - describe in notes	N		PUBLIC	Unable to obtain any documents or records to indicate service material type	Lead	0.75	1935	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER	
EPAL2636	WILLOW ST S 359	N	SF	Unknown - Likely Lead	UNK	UNK	1935	Other - describe in notes	N		PUBLIC	Unable to obtain any documents or records to indicate service material type	Non-Lead - Plastic	1.00	1935	INSTALLATION RECORD	Y	2022	VISUAL INSP AT METER	
EPAL2637	WILSON ST N 112	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2638	WILSON ST N 117	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2639	WILSON ST N 118	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2640	WILSON ST N 119	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2641	WILSON ST N 124	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2642	WILSON ST N 127	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2643	WILSON ST N 128	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2644	WILSON ST N 132	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2645	WILSON ST N 137	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2646	WILSON ST N 138	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2647	WILSON ST N 141	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2648	WILSON ST N 148	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2649	WILSON ST N 204	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2650	WILSON ST N 216	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2651	WILSON ST N 222	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2652	WILSON ST N 304	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2022	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP DURING INSTALL OR REPAIR		
EPAL2653	WILSON ST N 314	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2654	WILSON ST N 318	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2655	WILSON ST N 322	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2656	WILSON ST N 328	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2657	WILSON ST N 340	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2658	WILSON ST N 342	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2659	WILSON ST N 352	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2660	WILSON ST N 356	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2661	WILSON ST N 358	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Copper	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2662	WILSON ST N 362	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2663	WILSON ST N 364	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2664	WILSON ST N 372	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2665	WILSON ST N 374	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2666	WILSON ST N 382	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2667	WILSON ST N 384	N	SF	Non-Lead - Plastic	UNK	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2018	VISUAL INSP DURING INSTALL OR REPAIR	Non-Lead - Plastic	1.00	2018	INSTALLED AFTER LEAD BAN	Y	2022	VISUAL INSP AT METER		
EPAL2668	WINDFLOWER WAY 600	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2669	WINDFLOWER WAY 601	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2670	WINDFLOWER WAY 630	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2671	WINDFLOWER WAY 631	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2672	WINDFLOWER WAY 660	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2673	WINDFLOWER WAY 661	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2674	WINDFLOWER WAY 690	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2675	WINDFLOWER WAY 691	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2676	WINDFLOWER WAY 710	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2677	WINDFLOWER WAY 711	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2678	WINDFLOWER WAY 720	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2679	WINDFLOWER WAY 721	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2680	WINDFLOWER WAY 725	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2681	WINDFLOWER WAY 730	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2682	WINDFLOWER WAY 731	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2683	WINDMILL DR 528	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2684	WINDMILL DR 533	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2685	WINDMILL DR 534	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2686	WINDMILL DR 540	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2687	WINDMILL DR 546	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2688	WINDMILL DR 548	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2689	WINDMILL DR 551	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2690	WINDMILL DR 552	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2691	WINDMILL DR 558	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2692	WINDMILL DR 604	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2693	WINDMILL DR 607	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2694	WINDMILL DR 610	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2695	WINDMILL DR 616	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2696	WINDMILL DR 622	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2697	WINDMILL DR 628	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2698	WINDMILL DR 634	N	SF	Non-Lead - Copper	N	1.00	1985	Installation record	Y	1985	VISUAL INSP DURING INSTALL OR REPAIR	Unknown - Likely Lead	UNK	1985	Other - describe in notes	N			Unable to obtain any documents or records to indicate service material type	
EPAL2699	WINDMILL DR 640	N	SF	Non-Lead - Copper	N															